United States of America

Department of Transportation — Jederal Aviation Administration

Supplemental Type Certificate

Number

ST 768 SO

Added Notes at Surrender:

Future unsafe conditions existing in the product can result in an airworthiness directive requiring correction of the unsafe condition before further flight. If there is no entity to comply with 14 CFR 21.99(a), Required design changes, the existence of an unsafe condition might result in permanently grounding of the aircraft.

Replacement parts might not be available in the

This certificate, issued to

AERONAUTICAL ENGINEERS, INCORPORATED

certifies that the change in the type design for the following product with the limital toy

therefor as specified hereon meets the airworthiness requirements of Part 45 * CAR 4b dated December 31, 1953; Amendments 4b-1

through 45-10 thereto.

Original Product - Type Certificate Number:

STC Surrender processed:

GENERAL DYNAMICS

Model:

Date: 6/12/2009

Description of Trype Design Change:

Installation of a cargo loading door (forward L.H. side of fuselage)

in accordance with data shown in Arronautical Engineers, Inc.

Drawing List Report R-463 dated September 8, 1978.

Limitations and Conditions

Airworthiness compatability of the design change in accordance with this STC and other previous changes to the basic airplane models shown above, should be ascertained the change per this STC. prior to installation

k supporting data which is the basis for approval shall remain in effect until surded, revoked, or a termination date is otherwise established by the Administrator of the

Gederal Aviation Administration.

Date of application: June 19, 1978

Sinte reissued :

Date of issuance:

October 26, 1978

Sale amended:

By direction of the Administrator Walter Friedrich WALTER FRIEDMAN

Chief, Miami EMDO-43

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.